

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
02	007	023	0000002270	See list below	Appliance inlet 16A	GSP4

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected							
GSP4.0107.10	GSP4.0107.11	GSP4.0107.13	GSP4.010C.11	GSP4.010C.13	GSP4.0117.13	GSP4.0205.10	GSP4.0205.13
GSP4.0207.10	GSP4.0207.13	GSP4.0207.16	GSP4.020C.10	GSP4.020E.13	GSP4.0210.13	GSP4.0217.10	GSP4.0217.13
GSP4.0217.16							


2 Type of change

Modification of approval marks.


3 Detailed description of change

Change of rated current acc.to UL 60320. New rated current for cURus is 20A.
New combined cURus approval mark instead of separate UR and CSA marks.

Old marking



New marking



4 Reason of change

Change of rated current acc. to UL 60320.

5 Released date

The change will be rolled-out individually by all part numbers affected starting ww 50/2015 and last approx. 9 months.

6 Impact of change and recommended action

Form	No	No change in the form
Fit	No	There are no dimensional changes
Function	No	No change in the specification
Production Site	No	There is no change of the production site
Product Label	Yes	CSA and UR marks replaced by cURus mark.
Customer Action	No	No customer action required

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
GSP4 Data Sheet		

GSP4 Appliance Inlet					0118.2310	
creation date	created by	release date	released by	notification no.	revision	page
2015-09-11	hotzar	2015-10-22	hotzar	27860		1 of 1